

Retrofitting Existing Municipal Buildings City of Cambridge Municipal Facilities Improvement Plan



CITY OF CAMBRIDGE

Area: Population: Portfolio: 6.4 square miles118,403 Residents71 City Owned Buildings



Building Portfolio



Building Portfolio



Assessment Framework



Energy

GHG Emissions



Building Systems



IEQ



Historic Preservation



Accessibility

FS


Fire & Life Safety

CANIBRIDGE DEPARTMENT OF PUBLIC

2016 Assessment

Building Portfolio Assessment Matrix

| Building Level Tool | | Assessment Categories | | | | | | IEQ Subcategories | | | | Building Systems Subcategories | | | | | Vulnerability | | | | | | |
|--|------------------|-----------------------|--------------|--------------|---------------|-----|----------|-------------------|---------|-------------|----------|--------------------------------|--------------|--------------|--------------|------------|---------------|------------|----------|------------|---------------|------------------------------|---------------------------------|
| Partfolia Level Tool | Overall Score | 2015 EUI | 2015 GHG | Historic | Accessibility | IEQ | Building | Fire and Life | Thermal | Air Quality | Lighting | Acoustic | General | Exterior | Interior | Structural | Mechanical | Electrical | Plumbing | Flood Risk | Flood Risk | Heat Risk | |
| Building Name | | (kBtu/sf/yr) | (CO2e/sf/yr) | Preservation | | | Systems | Safety | Comfort | | | | Satisfaction | Architecture | Architecture | Systems | Systems | Systems | Systems | 2030 | 2070 | 2030 | 2070 |
| East Cambridge Fire House | -1 | -1 | 0 | 0 | -3 | -1 | 0 | -1 | 2 | 1 | 0 | -2 | -1 | 0 | 0 | 1 | 0 | -1 | 0 | V1 | V1 | VO | V1-V2 |
| Forter Square Fire House | -1 | 0 | 0 | 1 | -3 | 0 | 0 | -3 | -1 | -1 | 1 | -1 | -1 | 1 | 0 | 1 | 0 | -1 | 0 | V1 | V1 | V1-V2 | V1-V2 |
| Ire Headquarters | -1 | 0 | 0 | 0 | -2 | 0 | 0 | -3 | 0 | -1 | 1 | -1 | -1 | 0 | 0 | 1 | -1 | 0 | 1 | V2 | V2 | V1-V2 | V3-V4 |
| Lafayette Square Fire House | -1 | 0 | 0 | 1 | -3 | -1 | 0 | -1 | -1 | 2 | 1 | -1 | -2 | 1 | 0 | 1 | -1 | 0 | 1 | V1 V3 | V1-V3 | V1-V2 | V1-V2 |
| Lexington Avenue Fire House | -1 | D | 0 | 1 | -3 | 2 | 0 | -3 | 2 | 2 | 2 | 2 | 1 | 0 | 0 | 1 | -1 | -1 | -1 | V1 | V1 | VO | VO |
| liver Street Fire House | 0 | 0 | 1 | 2 | -3 | 1 | 0 | -2 | 1 | -1 | 2 | 0 | 0 | 0 | 0 | 1 | -1 | 0 | 0 | V1 | V1-V3 | VO | V1-V2 |
| Inman Square Fire House | 0 | 1 | 2 | 2 | -3 | -1 | 0 | -2 | - 1 | -1 | 0 | 1 | 2 | 0 | 0 | 1 | -1 | -1 | 0 | V1-V3 | V1-V3 | V1-V2 | V1-V2 |
| raylor Square Fire House | 0 | -1 | 0 | 2 | -3 | 1 | 1 | 1 | 0 | 1 | 1 | 1 | 1 | 1 | 0 | 1 | 0 | 0 | 2 | V1-V3 | V1-V3 | VO | V1-V2 |
| obert W. Healy Fublic Safety Blog. | 0 | 0 | -1 | 0 | 1 | 0 | 1 | 0 | 4 | 0 | 0 | 0 | 1 | 1 | 1 | 1 | -1 | 1 | 1 | V3-V5 | V3-V5 | V3-V4 | V3-V4 |
| Collins Branch Library | 1 | 0 | 0 | 2 | -1 | 0 | 0 | 3 | 1 | 1 | 1 | 1 | 0 | 1 | 1 | 1 | -1 | -1 | 0 | | | | |
| Cambridge Fublic Library | D | .1 | -1 | 2 | 1 | 1 | 1 | -2 | 1 | 1 | 1 | 4 | 2 | 1 | 1 | 1 | 1 | 2 | 2 | 22 | 12 | | 1 |
| O'Connell Branch Library | 1 | D | 1 | 2 | 0 | 2 | 0 | -3 | 2 | 2 | 2 | 2 | 1 | 1 | 1 | 1 | ō | 0 | 4 | - | | | |
| Boudreau Branch Library | 1 | 2 | 2 | õ | 0 | | 0 | 2 | | - | | | - | 0 | 0 | 1 | 0 | -1 | 0 | | | 2 | 1 |
| Central Square Branch Library | 1 | 2 | 2 | 1 | -2 | 0 | 0 | -1 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 1 | -1 | .2 | 1 | | | | |
| O'Neill Branch Library | 1 | 0 | 1 | 0 | 0 | 1 | 1 | -1 | 0 | 2 | 2 | 1 | 0 | 1 | 1 | 1 | 1 | 1 | 0 | | 12 1 | 1 | - |
| Moses Youth Center | -1 | 1 | - 1 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 1 | 1 | 1 | 1 | V2 | V2 | V3-V4 | V3-V4 |
| Frisoli Youth Center | 0 | | -1 | 0 | 0 | | 0 | 4 | 1 | 1 | - | 0 | - | 0 | 0 | | 0 | -1 | 1 | V2 | V2 | V1-V2 | V3-V4 |
| | | -1 | 0 | 0 | 1 | 0 | 0 | 1 | -1 | 0 | 0 | 0 | -1 | 0 | 0 | 1 | -1 | -1 | 0 | V2 V2 | V2 | V1-V2 | V3-V4 |
| Noore Youth Center Russell Youth and Community Ctr. | 1 | 0 | 0 | 0 | 1 | 1 | 1 | -1 | -1 | 2 | 1 | 0 | 2 | 1 | | 1 | 1 | 1 | 1 | V2 V2 | V2 V2 | V1-V2 V1-V2 | V3-V4 |
| Titywide Senior Center | | | 1000 | 1 | 1 | 1 | 1 | -1 | -1 | | 1 | | | 0 | 0 | 1 | | 0 | | V2 V1 | V2 V1 | and the second second second | the second second second second |
| | 1 | -4 | -1 | | | - | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 0 | | 1 | 1 | 1 | | | Not Assessed | |
| Gately Youth Center | 1 | 2 | 2 | 0 | -2 | 1 | | | 0 | 2 | 1 | 0 | 1 | - | -1 | 1 | | -1 | | V2 | V2 | V3-V4 | V3-V4 |
| North Cambridge Senior Center | | - | | | 0 | - | 0 | -1 | | | 2 | 1 | 1 | 1 | | | -1 | -1 | 0 | | | -27 | 10 |
| Cemetery Administrative Building | -2 | -2 | -2 | 1 | -3 | 1 | 0 | -3 | 2 | -1 | 2 | 0 | 1 | 1 | 0 | 1 | -1 | -1 | 0 | | | • | |
| Corporal Burns Building | -2 | 1 | 0 | -1 | -3 | | -1 | -5 | | | | | - | 0 | -1 | 1 | -1 | -2 | 2 | - | 14 | | |
| DFW Frazier Acministrative Bidg. | -1 | -1 | 0 | 0 | -2 | 0 | 1 | -2 | -1 | 0 | 1 | 0 | -1 | 1 | 0 | 1 | 1 | -1 | 1 | - | | | 1 |
| Lombardi Building | -1 | -1 | -1 | 1 | 0 | 0 | 0 | -2 | -1 | 0 | 0 | 0 | -1 | 0 | 0 | 1 | 0 | -1 | 1 | - | | - | - |
| Coffon Building | 0 | 1 | | 1 | 0 | 0 | 0 | -3 | -1 | 0 | 0 | | 0 | 1 | 1 | 1 | -1 | -2 | -1 | V2 | V2 | V1-V2 | V3-V4 |
| City Hall Annex | 0 | 0 | 0 | 1 | -1 | 0 | 1 | -1 | -1 | 0 | 1 | 0 | 0 | 0 | 1 | 2 | 1 | 1 | 2 | V1 | V1 | VO | V1-V2 |
| City Hall Building | 0 | 0 | 0 | 3 | -1 | 0 | 0 | -1 | -1 | 0 | 0 | -1 | 1 | 1 | 1 | 1 | -1 | -1 | 0 | V1 | V1 | VO | V1-V2 |
| Alice K. Wolf Center | 1 | 1 | 1 | 2 | 1 | 1 | 1 | 0 | 0 | 1 | 1 | 1 | 1 | 1 | 1 | 1 | 2 | 1 | 2 | - | | | 1 |
| Cemetery Garage | -2 | -2 | -2 | 1 | -1 | | 0 | -3 | | | | | | 1 | 0 | 1 | -1 | -1 | 0 | -8 | | - | |
| DPW Garage | 1 | -1 | 0 | 1 | -2 | -1 | 0 | 0 | 0 | 2 | 0 | -2 | -1 | 0 | 0 | 1 | -1 | -1 | 0 | | | - | 1 |
| First Street Parking Garage | 1 | 2 | 2 | 1 | -1 | | 0 | -2 | | - | | | - | 0 | 0 | 1 | -1 | 0 | 1 | V1 | V1 | V1 | V1 |
| Green Street Garage | 1 | 2 | 2 | 0 | 1 | | 0 | 1 | | 51 3 | - | 2 | 1 | 0 | 0 | 1 | 0 | -1 | 1 | V1 | V1 | V1 | V1 |
| Kennedy-Longfellow School/PAUS | 2 | 0 | 0 | 0 | -3 | -1 | 0 | Э. | 2 | -2 | 0 | 1 | -2 | 0 | -1 | 2 | 0 | -1 | 0 | V1-V3 | V1-V3 | V1 V2 | V1-V2 |
| Peabody School/RAUS | 0 | 0 | 0 | 0 | -1 | 1 | 1 | 0 | 0 | 1 | 1 | 0 | 1 | 1 | 0 | 1 | 0 | 1 | 1 | V1 | V1 | V1-V2 | V1-V2 |
| Cemetery Chapel | -2 | -2 | -2 | 1 | -3 | - | 0 | -3 | 1 | S | | 8 | | 1 | 0 | 1 | -2 | - 1 | 0 | | | - 42 | 6 |
| The Shop - Electrical Department | -2 | 2 | 2 | -2 | -3 | -1 | -2 | | -1 | -1 | 0 | -1 | -1 | 0 | -2 | -3 | -2 | -2 | 0 | | | | |
| DPW Simard Building | -1 | -1 | 0 | 0 | -3 | 1 | 0 | -8 | 1 | 1 | 2 | 1 | 1 | 1 | 0 | 1 | -1 | -1 | 1 | | | | 10 10 |
| Solf Course Clubhouse | -1 | -2 | -1 | -1 | 0 | 0 | 0 | 0 | 0 | -2 | 1 | -1 | -1 | 1 | D | 1 | -1 | 0 | 0 | +0 | | • | |
| Daneby Park Comfort Station | -1 | -1 | 2 | 0 | -2 | 2 | 1 | -2 | 2 | 2 | 2 | 2 | 2 | 1 | 0 | 1 | 1 | -1 | 1 | | . (a. 1 | | 5 |
| First Street Parking Garage Retail | 0 | 2 | 2 | 1 | -1 | -1 | 0 | -2 | 0 | -1 | 0 | -1 | -1 | 1 | 0 | 1 | -1 | 0 | 1 | | (A) | | 1 |
| Golf Course Tip O'Neill Maint. Blog. | 1 | 2 | 2 | 0 | 1 | 2 | 0 | -1 | 3 | 0 | 3 | 2 | 1 | 0 | 0 | 1 | 0 | 0 | 1 | | | | |
| e Score for City of Cambridge Portfolio | -1 | 0 | 0 | 1 | -1 | 0 | 0 | -1 | 0 | 0 | 1 | 0 | 0 | 1 | 0 | 1 | 0 | -1 | 1 | | | | |
| | 2 | | | | | | | | | | | | 1 | | | | | | | | Vulnerability | | |
| | | | -7 | -1 | D | | | | | | | | | | | | | | | | | ty (low - high S1 S2 | |



ARUP

→ best

2016 Assessment

Recommendations (Sample)

CNMBRIDGE DEPARTMENT DEPARTMENT OF PUBLIC **City of Cambridge - Department of Public Works Municipal Facilities Improvement Plan** Site Assess

| Municipal Facilities Improve | | | | | | Immediate Recommendation Additional Opportunity | | | | | | |
|--------------------------------------|---------------|--------------|-------------------|------------------|---|--|------------------------------|-----------------------|------------------------|--|--|--|
| Site Assessment Recomment | tations | | | | | Additional opportunity | | | | | | |
| Building Name | Typology | Area (SF) | Community Use? | Overall Score | ARCHITECTURE | | | | | | | |
| East Camoridge Fire House | Public Safety | 17,093 | No | -1 | Window Lintels: Re-paint | Window Replacment: | Door Repairs: Re-paint | Interior finishes: | Interior Finishes: Re- | | | |
| Porter Square Fire House | Public Safety | 11,213 | No | -1 | Door Repair: One | Sealant Work: Sealants | Interior Finishes: Vinyl | Interior Finishes: | | | | |
| Fire Headquarters | Public Safety | 30,389 | Yes | -1 | Roof Replacement: The | Façade Masonry: Masonry | Sealants: Sealants are | | | | | |
| Lafayette Square Fire House | Public Safety | 19,080 | No | -1 | Window Repairs: Paint | Interior Finishes: Insulate | Interior Finishes: Replace | Roof: Snow Guards. | Sealants: Sealants | | | |
| Lexington Avenue Fire House | Public Safety | 6,525 | No | -1 | Window Repairs: Instal | Interior Finishes: Repair | Sealants: Replace sealants | Interior Finishes: | Door Repairs: Replac | | | |
| River Street Fire House | Public Safety | 9,643 | No | D | External Doors: Exterior | Interior Finishes: Replace | | | | | | |
| Inman Square Fire House | Public Safety | 16,728 | No | 0 | Sealants: Replace sealants | Window Repairs: Instal | Roof Replacement: | Door Repairs: Repaint | Interior Finishes: | | | |
| Taylor Square Fire House | Public Safety | 16,187 | No | 0 | Roof Repair: Water: | | | | | | | |
| Robert W. Healy Public Safety Bldg. | Public Safety | 162,547 | Yes | 0 | Window Upgrades: We | Door Repairs: Add | Green Roof Maintain: The | | | | | |
| Collins Branch Library | L'brary | 3,300 | Yes | -1 | Window Replacement: The | | | | | | | |
| Cambridge Public Library | Library | 277,185 | Yes | 0 | Window Replacement: | | 6 | | | | | |
| O'Connell Branch Library | L'brary | 6,427 | Yes | 1 | Roof PV System addition: | | | | | | | |
| Boudreau Branch Library | Library | 1,955 | Yes | 1 | Door Replacement: | Interior Repairs: Repair | Interior Finishes: Ceiling | | | | | |
| Central Square Branch Library | L brary | 15,447 | Yes | 1 | Window Replacement: The | | U | | | | | |
| O'Nell Branch Library | L brary | 4,566 | Yes | 1 | Masonry Repairs: Repair | Door Replacement: | Sealant Work: Replace | | | | | |
| Moses Youth Center | Youth Center | 19,405 | Yes | -1 | and the second se | Interior Finishes: Replace | | | | | | |
| Frisoli Youth Center | Youth Center | 20,059 | Yes | D | Door Hardware Repairs: | Window Hardware Repair: | Interior finishes: Walls: | Roof Replacement: | Inter or finishes: | | | |
| Moore Youth Center | Youth Center | 10,537 | Yes | 1 | Roof Replacement: The | | | | | | | |
| Russell Youth and Community Ctr. | Youth Center | 31,586 | Yes | 1 | Windows/Glazing: Solar | | | | | | | |
| Citywide Senior Center | Senior Center | 27,999 | Yes | 1 | | Sealant Work: Replace | Interior Finishes: Areas of | | | | | |
| Gately Youth Center | Youth Center | 14,837 | Yes | 1 | Sealant Work: Sealants | Interior Finishes: The wood | | | | | | |
| North Cambridge Senior Center | Senior Center | 3,623 | Yes | 1 | Sealant Work: Replace | Interior Finishes: Replace | | | | | | |
| Cemetery Administrative Building | Office | 2,874 | Yes | -2 | Window Repairs: Further | Sealant Work / G azing: | Interior finishes: Caroeted | | | | | |
| Corporal Burns Bu'lding | Office | 3,591 | No | -2 | Entry Stair Repairs: The | Window Replacements: | Door Replacements: | Tr'm Rep acements: | General: Al | | | |
| DPW Frazier Administrative Bldg. | Office | 12,550 | Yes | -1 | Storefront Replacement: | Interior finishes: (floors | | | | | | |
| Lombard' Building | Office | 21,808 | Yes | -1 | Roof Replacement: Rubber | Sealant Work: Sealants | Interior finishes: Flooring: | | | | | |
| Coffon Building | Office | 31,240 | Yes | 0 | Roof Replacement: The | Interior Finishes: Replace | Interior finishes: Replace | | | | | |
| City Hall Annex | Office | 33,909 | Yes | 0 | Window Repair: Address | Masonry Repairs: Step | Roof and Wall Leakage: | Sealant Work: Some | Interior Finishes: A | | | |
| City Hall Bui ding | Office | 61,731 | Yes | 0 | Interior Insulation: | Window Replacement: | Flooring Replacement: The | | | | | |
| Al'ce K. Wolf Center | Office | 58,318 | Yes | 1 | | | 3 S | | | | | |
| Cemetery Garage | Garage | 1,830 | Yes | -2 | Interior Finishes: Flooring: | Interior Finishes: Walls: | | | | | | |
| DPW Ryan Garage | Garage | 44,547 | No | -1 | Masonry Repairs: It is | Interior finishes: Floors and | | | | | | |
| First Street Parking Garage | Garage | 378,000 | Yes | 1 | Sealants & Control Joints: | | e Door Replacement: Metal | Interior Finishes: | | | | |
| Green Street Garage | Garage | 110,884 | Yes | 1 | Sealant Work: Sealants on | Interior finishes: All: | | | | | | |
| Kennedy-Longfellow School/PAUS | School | 127,302 | Yes | •Z | Masonry Repairs & | Storefront Entrance | Envelope & Window | Celling & flooring | Interior Finishes: | | | |
| Peabody School/RAUS | School | 108,989 | Yes | 0 | Interior Finishes: Wood | Sealant Work: The sealants | Root Replacement: The | | | | | |
| Cemetery Chapel | Other | 1,923 | Yes | -2 | Window Repairs: | Interior Finishes: Vinyl | | | | | | |
| The Shop - Electrical Department | Other | 8,418 | No | -2 | Window Replacements: | Door Replacements: | Roof Replacment: The flat | Cornice Replacement: | Interior Finishes: | | | |
| DPW Simard Building | Other | 11,542 | No | -1 | Interior finishes: Floors and | | | | | | | |
| Go f Course Cluphouse | Other | 4,610 | Yes | -1 | Door Replacement: The | Roof Repair: Isolated areas | Window Repairs: Some | Window Repairs: | Sealant Work: There | | | |
| Daneny Park Comfort Station | Other | 1,696 | Yes | -1 | Masonry Repairs: Some | Window Repairs: One | | | | | | |
| First Street Parking Garage Retail | Other | 8,909 | Yes | D | Interior Finishes: The retail | | | | | | | |
| Go If Course Tip O'Neill Main. Bldg. | Other | 4,319 | No | 1 | Envelope Thermal | Sealant Work: Sealants | Roof Repairs: The wood | Doors: The wood trim | Doors: The wood trin | | | |



Approach

Project Classifications:

Large Scale Renovations

Greatest Needs, addressed through major alterations.

Net Zero Emissions requirement applies

\$5 to \$50M Project Budget Small Scale Renovations

Improvement projects to address accessibility, fire & life safety, controls, or a combination. Target electrification & on-site renewables whenever feasible.


> \$500,000 - \$5.0M Project Budget

Deferred Maintenance

Projects to address envelope and equipment that are at or beyond useful life, such as roofs, sealants, equipment, or interior finishes and fixtures

> \$50,000 - \$2.0M Project Budget

Net Zero and BEUDO



GHG reduction target

Net Zero and BEUDO

Paths to Net Zero:

2035:

- ~86% GHG Emissions reduction target
- Ongoing Capital Improvement Projects to electrify Gas and Oil Systems and improve building efficiency
- Renewable Electricity Purchase: Certified investments in clean, renewable energy
- Carbon Offsets as required to meet any shortfalls to 2035 target

2050:

- 100% Net Zero Emissions
- Capital Improvements required to full portfolio of BEUDO buildings (25,000 sf and up) to electrify building systems and Eliminate gas and oil use




Funding Sources

The **City of Cambridge** self-funds much of our building improvements using **general obligations bonds** or **free cash appropriations** (for items that are supplemental to the annual budget).

However, the City does utilize additional sources of funding, including:

- DOER Green Community Grants
- Eversource Rebates for energy efficiency projects
- Revenue from DOER's Alternative Energy Credits (AECs) program







CASE STUDIES

Lexington Avenue Firehouse

167 Lexington Avenue



1893

Original Completion: Previous Renovations: Historic: Internal Area: Function: Occupants:

Areas of Need:

N/A -6,525 sf Firehouse Fire Department: Engine 9 Architectural Mechanical Electrical Fire & Life Safety Current Project: Status: Project Completion Date: Construction Cost:

Full Renovation COMPLETE 2022 \$3.4 million

Current Scope of Work:

- Exterior masonry re-pointing
- Roof replacement
- Complete interior renovation, including:
 - New kitchen
 - Decontamination showers
 - Sleeping Quarters
 - Common Area
 - Gym
 - Engine Bay
- All-electric HVAC systems
- Energy-efficient LED Lighting
- Driveway repaving

Future Upgrades:

Window replacement

Moses Youth Center

243 Harvard Street



Original Completion: Previous Renovations: Historic: Internal Area: Function:

Occupants: Areas of Need: 1991 -No 22,000 sf Youth & Day Care Center Community HVAC Roof Facade Current Project: Status: Project Completion Date: Est. Construction Cost: HVAC Upgrade & Repairs FEASIBILITY 2025 \$5 million

Current Scope of Work:

- Full HVAC replacement (all-electric)
- Partial roof replacement
- Slate Roof repairs
- Partial Window and Door seals
- Feasibility Study for façade and interior improvements

Challenges:

- Occupied building
- HVAC beyond useful life
- Significant other needs beyond HVAC



DPW Simard Building

147 Hampshire Street



Original Completion: 1977 Previous Renovations: 1989, 1993, 2002, 2005 Historic: No Gross Internal Area: 11,542 sf Function: DPW Offices, Workshop, Occupants: Sign Shop, Storage Areas of Need: Space Planning, Envelope, Energy, IEQ, MEP, Accessibility

Current Project: Status: Project Completion Date: Est. Construction Cost:

Current Scope of Work:

- Envelope Repair & Upgrades
- Full interior renovation
- All-Electric Building
- Rooftop PV Array
- Geothermal Wells

Full Renovation CONSTRUCTION Fall 2023 \$8 million

Fire Headquarters

491 Broadway



Original Completion: Previous Renovations: Historic: Internal Area: Function: Occupants:

Areas of Need:

1933 1990, 2009, 2012 Yes 30,389 sf Firehouse Fire Department: Engine 1, Ladder 1, Rescue 1 Mechanical, Fire & Life Safety Accessibility Roof Current Project: Status: Project Completion Date: Est. Construction Cost: Full Renovation DESIGN Winter 2025 \$47 million

Current Scope & Targets:

- All-electric (Net-Zero emissions)
- LEED Gold renovation
- Envelope: Roof replacement, windows, masonry
- Equipment bay slab lowering
- Interior renovation, including:
 - Equipment bay
 - Sleeping Quarters
 - Common Area
 - Kitchen
 - Decontamination showers
 - Gym
- Rooftop Photovoltaic array
- Ground source heat pumps
- EV Charging stations



Conclusions & Commentary

- Energy & Sustainability Goals: Easier to achieve in new construction, existing building retrofits are more difficult, more costly, and there are many competing needs and logistical challenges
- For existing buildings with significant other maintenance and repair needs, recommend <u>Net-Zero "over time"</u> approach – preferable to implement phased improvements addressing multiple building issues in one project, rather than targeting "quick-fix" systems electrification projects that are not in the long-term best interests of the building or its occupants, and don't address other critical needs.

THANK YOU